

DR. LEWIS

UGI

SUPPLIES: CRYSTALS w Tbsp water (2 sm. Cups)
POLIBAR (Thick ba) $\frac{1}{4}$ cup
POLIBAR Diluted (thin BA) 6 oz w/ straw
CUP of WATER w/ straw
Paddle and right glove on counter

PROCEDURE: Show Dr. Scout
GIVE patient crystals w/water, then thick BA
Lie Patient down and roll over to coat stomach
TAKE OVERHEADS, SEND images to Dr.
START Patient **RAO** w/ Cup of thin Ba and straw
After Dr.s spots, PATIENT slight RPO
TECH at head of table w/ cup of water, gives
Patient 2 sips for reflux test

OVERHEADS: AP
RT LATERAL
PA
RAO