

## **DR. FENNELL**

### **UGI**

#### **SUPPLIES**

POLIBAR thick BA ¼ cup  
POLIBAR diluted 6oz w/ straw  
CRYSTALS w/ 1 Tbsp water in (2) small cups

#### **PROCEDURE**

Start UPRIGHT. Tech to use fluoro capture on Esoph images. LIE patient/table down, roll patient one time. Last patient RAO, give cup of thin Ba w/ straw, Tech fluoro captures esoph images. TAKE OVERHEADS.

#### **OVERHEAD IMAGES**

1. PA
2. RAO
3. RIGHT LATERAL

If all anatomy on overheads you may have patient leave.